



No Fault Out
 spare
 spare
 spare
 Spindle Fault Reset
 Spindle Orient
 Spindle Run
 spare
 spare



192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215



| | | | |
|---|--------|---------------|-------------|
| MACHINE | | | |
| Quickmill "Quickdrill" with Centroid M400 | | | |
| DRAWN BY | SIZE | REV | DATE |
| Marc Leonard | D | 1 | 26-Jan-2024 |
| SCALE | SHEET | FILE | |
| none | 3 OF 3 | K104810_3.VCD | |