

Oil Mist Solenoid (Spindle Bearing Lube)

Low Gear Solenoid

High Gear Solenoid

spare

Spindle Tool Unclamp

Y Axis Clamp Solenoid

Y Axis Unclamp Solenoid

Z Axis Clamp Solenoid

Spindle Air Blow Solenoid

Coolant Solenoid (optional)

Spindle Brake

spare


spare

spare

spare

Work Light

spare



Magazine CW

Magazine CCW

Arm CCW

Arm CW

Arm Up

Arm Down

Arm Left

Arm Right


Magazine Tool Holder Unclamp Solenoid

Magazine Tool Auto Position Unclamp

Magazine Tool Manual Position Unclamp

Magazine Panel Auto-Mode Lamp (optional)

ATC Panel Auto-Mode Lamp



spare

spare

spare

spare

spare

spare

spare

spare

spare

spare

spare

spare

spare

spare

spare

spare

spare

MACHINE			
SNK RB-2N Gantry Mill w/ Centroid M400 Control			
DRAWN BY	SIZE	REV	DATE
Marc Leonard	D	1	27-May-2021
SCALE	SHEET	FILE	
none	4 OF 4	K104065_4.VCD	